

2016 Test Results

MALCOM BELL (LOWER)

40 BALDWIN RD

New Bubbler or new fixture Installed

SAMPLE LOCATION	First Draw	30 second flush	First Draw	30 second flush
	Lead Level (Pb Final)	Lead Level (Pb Final)	Lead Level (Pb Final)	Lead Level (Pb Final)

Room 1 Bubbler	15.2 ug/L	2.68 ug/L	2.20 ug/L	2.28 ug/L
Room 2 Bubbler	7.76 ug/L	1.85ug/L		
Room 4 Bubbler	8.28 ug/L	2.16ug/L		
Room 5 Sink	20.3 ug/L	3.99 ug/L	3.99 ug/L	3.27ug/L
Room 6 Bubbler	264 ug/L	10.5 ug/L	4.86 ug/L	3.74 ug/L
Room 3 Bubbler	5.57 ug/L	3.19ug/L		
bubbler H.W.	8.24 ug/L	1.62ug/L		
Nurse Sink	31.2 ug/L	5.25 ug/L	4.22 ug/L	3.08 ug/L
K-RM Sink	3.09 ug/L	2.64ug/L		
Kitchen Sink	<1.00 ug/L	<1.00ug/L		

EPA - DEP ACTION LEVEL 15.5 ug/L

30 second flush sample completed

2018 Test Results

MALCOM BELL (LOWER)

40 BALDWIN RD

SAMPLE LOCATION	First Draw	30 second flush
	Lead Level (Pb Final)	Lead Level (Pb Final)

Room 1 Bubbler	5.7 ug/L	1.94 ug/L
Room 2 Bubbler	1.72 ug/L	1.76 ug/L
Room 4 Bubbler	18.1 ug/L	3.81 ug/L
Room 5 Sink	6.55 ug/L	5.7 ug/L
Room 6 sink	19 ug/L	3.67 ug/L
Room 3 Bubbler	7.28 ug/L	1.64 ug/L
bubbler H.W.	8.82 ug/L	1.6 ug/L
Nurse Sink	81.9 ug/L	17.7 ug/L
K-RM Bubbler	5.66 ug/L	5.56 ug/L
Kitchen Sink	6.32 ug/L	3.96 ug/L

Bell School water bubblers have been all disconnected/turned off.

Drinking water provided through stand alone water coolers.